MR. PULIYOOR T. P. VELAYUDHAN PILLAI: May I know whether the officer responsible for the construction of this bridge at Thottapalli is putting up the bridge with the same materials now?

MR. M. K. NILAKANTA AIYAR: Yes, the very same materials are being used.

New Bridge at Thottappally.

13. * MR. K. P. KOCHUKORATHARAKAN: Will the Government be pleased to state:

(*a*) whether they are aware of the breaking down of the new bridge under construction near the Thottappally Lock for transport purposes;

(*b*) whether they have made enquiries about the causes of the break down;

(*c*) if so, what was it due to, what loss the Government has to sustain thereby and the person responsible for it:

(*d*) whether the said bridge was constructed of iron, cement, or timber subjected to ascu treatment, or by combining any of these materials and, if so, which of them proved defective; and

(*e*) whether any serious injuries or death has been caused to labourers or others at the time when the bridge fell down and, if so, the nature of the injuries and the number of persons injured or dead?

MR. M. K. NILAKANTA AIYAR: (*a*) The structure fell down.

(*b*) Yes. Further enquires are being made.

(*c*) One out of the two boats that were supporting one end of the bridge, which was being pushed across the channel, suddenly gave way during the night of the 8th January 1939 on account of the collapse of a plank at the bottam of one of the boats. About Rs. 3,000. There was nobody who could be held resposible for it, as it was accidental.

(*d* Essentially of teak and Ascu treated maruthi. The accident was not due to any defect in the meterials used on the bridge.

(*e*) There was no casualty or any case of serious injury whatever.

MR. K. P. KOCHUKORATHARAKAN: എത്രത്തോളംഭാരം താങ്ങുമെന്നുള്ളതിനെപ്പറ്റി പരിശോധിച്ചു നോക്കേണ്ട ചുമതല ഉണ്ടായിരുന്നില്ലേ?

MR. M. K. NILAKANTA AIYAR: പരിശോധിക്കേണ്ട ചുമതല ഉണ്ടായിരുന്നു. പക്ഷേ ഇത് യാദൃശ്ചികമായി അപകടം സംഭവിച്ചതാണ്.

MR. K. P. KOCHUKORATHARAKAN: ഉദ്ദേശിക്കുന്ന തരത്തിലുള്ള ഭാരം കയറാത്തക്ക ശക്തി അതിനുണ്ടോ എന്നു പരിശോധിച്ചു നോക്കിയിട്ടുണ്ടോ?

MR. M. K. NILAKANTA AIYAR: ഇരുപതു ടൺഭാരം കയറാവുന്ന വള്ളത്തിൽ പതിനഞ്ചു ടൺ ഭാരമുള്ള പാലത്തിന്റെ ഒരു അറ്റംമാത്രമെ കയറിയുള്ളൂ.

LIBRARY ARCHIVES Kerala Legislative Assembly

MR. K. P. KOCHUKORATHARAKAN: ഈ പാലത്തിനു വല്ലവരുംകൂടി കേടുവരുത്തിയിട്ടുള്ളതാണോ എന്നറിയാമോ?

MR. M. K. NILAKANTA AIYAR : അങ്ങിനെ ഒരുകേഴ്വിയുണ്ട്. അതിനെപ്പറ്റി അന്വേഷിക്കുന്നുണ്ട്.

MR. K. P. KOCHUKORATHARAKAN : വള്ളത്തിന്റെ പലകയുംമറ്റും പൊളിഞ്ഞു കിടക്കുന്നതുകണ്ടാൽ കേടുവരുത്തിയതാണോ അല്ലയോ എന്ന് നിശ്ചയിക്കാമല്ലോ.

MR. M. K. NILAKANTA AIYAR : പ്രഥമദൃഷ്ടിയിൽ അതിനെപ്പറ്റിയാതൊരു സംശയവും കാണുന്നില്ല. എങ്കിലും അതിനെപ്പറ്റി അന്വേഷണം നടത്തുന്നുണ്ട്.

MR. K. R. NARAYANAN : കേടുവന്ന വള്ളം ഏതുകൊല്ലത്തിൽ പരിശോധിച്ചിട്ടുള്ളതാണെന്നറിയാമോ?

MR. M. K. NILAKANTA AIYAR : അതിനെപ്പറ്റി അന്വേഷിച്ചിട്ടില്ല.

MR. PULIYOOR T. P. VELAYUDHAN PILLAI: May I know from the Government whether any foul play was committed in connection with the fixing up of the exhibition bridge in Trivandrum during the Birthday week ?

PRESIDENT : Order, order, order. We are now discussing the Thottapally bridge.

MR. PULIYOOR T. P. VELAYUDHAN PILLAI : It was a similar bridge.

Irrigation tanks in the Kalkulam taluk.

14. * MR. C. JEBAMONY NADAR : Will the Government be pleased to furnish in a tabular form the following information in regard to (*a*) the Thiruvithamcode channel area under the Kodayar project, (*b*) the area fed by the P. P. channel and (*c*) the "Miscellaneous system" under the Kodayar project ;

(1) the names of irrigation blocks in the area ;

(2) the area of each block ;

(3) the average annual rainfall in each block for the last 15 years ;

(4) the names of irrigation tanks (if any) in each block ;

(5) the area of each of these tanks ;

(6) the present condition of these tanks ; whether they are maintained in full storage capacity or are silted up ; and

(7) the distance of each of these blocks (along the channels) from the Pachipara reservoir ?

MR. G. B. E. TRUSCOTT : Items (1), (2) and (4) to (7). A statement furnishing the information required is laid on the Secretary's table.

(3) No rain gauge is fitted in each block and hence the information is not available.

LIBRARY ARCHIVES Kerala Legislative Assembly